




Altecnic SATK30105 HE LTC as tested at SP (Jan 2016)

Test 1e: Poor radiator setup




Altecnic SATK30105 HE LTC as tested at SP (Jan 2016)

Test 1f: HIU optimised for poor radiator setup




Evinox MTP 55-20R as tested at SP (Jan 2016)

Test 1e: Poor radiator setup




Evinox MTP 55-20R as tested at SP (Jan 2016)

Test 1f: HIU optimised for poor radiator setup




Pegler Yorkshire GB00049 as tested at SP (Jan 2016)

Test 1e: Poor radiator setup




Pegler Yorkshire GB00049 as tested at SP (Jan 2016)

Test 1f: HIU optimised for poor radiator setup




SAV Termix VVX-I-FI-1-5 RAD STD as tested at SP (Dec 2015)

Test 1e: Poor radiator setup




SAV Termix VVX-I-FI-1-5 RAD STD as tested at SP (Dec 2015)

Test 1f: HIU optimised for poor radiator setup



Thermal Integration DATA Lite as tested at SP (Feb 2016)

Test 1e: Poor radiator setup



Thermal Integration DATA Lite as tested at SP (Feb 2016)

Test 1f: HIU optimised for poor radiator setup